



Notification of Hazardous Waste Site

6-29-81

PASSF 1.3v1
6/29/81
United States
Environmental Protection
Agency
Washington DC 20460

RECEIVED

WAS 000 000 032
JUN 05 '81 pmd 81-06-05

Solid Waste Mgmt.
EPA Region X

1.3

This initial notification information is required by Section 103(c) of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 and must be mailed by June 9, 1981.

Please type or print in ink. If you need additional space, use separate sheets of paper. Indicate the letter of the item which applies.

A Person Required to Notify:

Enter the name and address of the person or organization required to notify.

Name Resource Recovery Corporation
Street 5501 Airport Way So.
City Seattle State WA Zip Code 98108

B Site Location:

Enter the common name (if known) and actual location of the site.

Name of Site Pasco Landfill
Street Kahlotus Road
City Pasco County Franklin State WA Zip Code 99301

WATS 40010089

C Person to Contact:

Enter the name, title (if applicable), and business telephone number of the person to contact regarding information submitted on this form.

Name (Last, First and Title) Kimberly, John Pres.
Phone (206) 767-0355

D Dates of Waste Handling:

Enter the years that you estimate waste treatment, storage, or disposal began and ended at the site.

From (Year) 1972 To (Year) 1974

E Waste Type: Choose the option you prefer to complete

Option 1: Select general waste types and source categories. If you do not know the general waste types or sources, you are encouraged to describe the site in Item I—Description of Site.

General Type of Waste:

Place an X in the appropriate boxes. The categories listed overlap. Check each applicable category.

1. ☒ Organics
2. ☒ Inorganics
3. ☒ Solvents
4. ☒ Pesticides
5. ☒ Heavy metals
6. ☒ Acids
7. ☒ Bases
8. ☐ PCBs
9. ☐ Mixed Municipal Waste
10. ☐ Unknown
11. ☐ Other (Specify)

Source of Waste:

Place an X in the appropriate boxes.

1. ☐ Mining
2. ☐ Construction
3. ☐ Textiles
4. ☐ Fertilizer
5. ☐ Paper/Printing
6. ☐ Leather Tanning
7. ☐ Iron/Steel Foundry
8. ☒ Chemical, General
9. ☒ Plating/Polishing
10. ☐ Military/Ammunition
11. ☐ Electrical Conductors
12. ☐ Transformers
13. ☐ Utility Companies
14. ☐ Sanitary/Refuse
15. ☐ Photofinish
16. ☐ Lab/Hospital
17. ☐ Unknown
18. ☒ Other (Specify)

paint, mfg. solvent
reclaiming, resin mfg,
pesticide mfg, chlor-
alkali plant

Option 2: This option is available to persons familiar with the Resource Conservation and Recovery Act (RCRA) Section 3001 regulations (40 CFR Part 261).

Specific Type of Waste:

EPA has assigned a four-digit number to each hazardous waste listed in the regulations under Section 3001 of RCRA. Enter the appropriate four-digit number in the boxes provided. A copy of the list of hazardous wastes and codes can be obtained by contacting the EPA Region serving the State in which the site is located.



Notification of Hazardous Waste Site

Side Two

F Waste Quantity:

Place an X in the appropriate boxes to indicate the facility types found at the site.

In the "total facility waste amount" space give the estimated combined quantity (volume) of hazardous wastes at the site using cubic feet or gallons.

In the "total facility area" space, give the estimated area size which the facilities occupy using square feet or acres.

Facility Type

1. ☐ Piles
2. ☐ Land Treatment
3. ☒ Landfill
4. ☒ Tanks
5. ☐ Impoundment
6. ☐ Underground Injection
7. ☐ Drums, Above Ground
8. ☒ Drums, Below Ground
9. ☐ Other (Specify) _____

Total Facility Waste Amount

cubic feet 200,000 est.

gallons _____

Total Facility Area

square feet _____

acres 170

G Known, Suspected or Likely Releases to the Environment:


Place an X in the appropriate boxes to indicate any known, suspected, or likely releases of wastes to the environment.

☐ Known ☐ Suspected ☐ Likely ☒ None

Note: Items H and I are optional. Completing these items will assist EPA and State and local governments in locating and assessing hazardous waste sites. Although completing the items is not required, you are encouraged to do so.

H Sketch Map of Site Location: (Optional)

Sketch a map showing streets, highways, routes or other prominent landmarks near the site. Place an X on the map to indicate the site location. Draw an arrow showing the direction north. You may substitute a publishing map showing the site location.

**I Description of Site: (Optional)**

Describe the history and present conditions of the site. Give directions to the site and describe any nearby wells, springs, lakes, or housing. Include such information as how waste was disposed and where the waste came from. Provide any other information or comments which may help describe the site conditions.

The site is approximately 3 miles NE of Pasco WA.

There is a well on the site, one SE of the site and an irrigation well west of the site.

The site was run as a open/burning dump before 1972 and as a sanitary landfill since. The industrial wastes were buried in a separate area. The drums were buried as is and the liquids put in ponds, evaporated and then buried. All the industrial wastes were covered with poly-sheeting before burying. The operation was run under a waste discharge permit (zero discharge) issued by the Washington State Dept. of Ecology.

J Signature and Title:

The person or authorized representative (such as plant managers, superintendents, trustees or attorneys) of persons required to notify must sign the form and provide a mailing address (if different than address in item A). For other persons providing notification, the signature is optional. Check the boxes which best describe the relationship to the site of the person required to notify. If you are not required to notify check "Other".

Name Resource Recovery Corp.

Street 5501 Airport Way So.

City Seattle State WA Zip Code 98108

Signature John R. Kuhlberg

Date 6/29/81

- ☐ Owner, Present
☐ Owner, Past
☐ Transporter
☐ Operator, Present
☒ Operator, Past
☐ Other